## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established by Jacob C. Cooper in 1881 under General Land Office Contract No. 397.

Surveyor General Records (notes) states:

A tamarack 12 in. diam. on the south side of mountains 200 ft. below the summit in dense young timber which I marked for the 1/4 Section Corner, maked 1/4S on the East and West faces from which

Ins R.36E.
hich on the E

DIAGRAM

A fir 6 in. diam. bears  $828^{\circ}$ E, 14 lks. dist. marked 1/48 BT. A pine 12 in. diam. bears  $878^{\circ}$ W, 22 lks. dist. marked 1/48 BT.

Corners for TIS R37E ware set in subsequent survey.

(No subsequent remonumentations in county records)

## Description of corner evidence found:

Found a 24 in. tamarack with grown-over blazes on 4 sides, live, in good condition.

Found a 24 in. fir, live in good condition, with scribing visible, bearing \$280E 9 fc. from corner tree.

Found a 24 in. pine stump with scribing faintly visible, bearing N78 $^{\rm O}W$  14 ft. from corner tree.

## Description of monument and accessories I established to perpetuate the original location of this corner

No munument set as tree is in good condition, for East 1/4 Cor. Sec. 12

From which a new BT

A tamarack 20in. diem. bears S87°W, 63.5 ft. dist. marked TIS, R36E, 1/4S 12 FT.

Distance taken to a brass washer in the blaze of the tree.

Set a steel Tence post a proximately 5 ft. west from original corner trea with Forest Joundary sign attaches.

Used steel tame and magnetic compact with declination = 20°E.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON DOUGLAS M. FERGUSON 848

Office of County of County

Form R6-7100-57 (9/66)

H-152