## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1882 by Herman D. Gradon under General Land Office Contract No. 452.


Surveyor General Records (notes) states:

Set a basalt stone  $18 \times 8 \times 8$  ins. 12 ins. In the ground for 1/4 corner maked 1/4 on N face, from which

A fir 22 in. diam. bears N85°E 32 lks. dist. marked 1/4 S BT.

A fir 12 in. diam. bears S45°W 19 lks. dist. marked 1/4 S BT.

(No subsequent remonumentations in county records)



## Description of corner evidence found:

Found 36 in. fir, live in good condition, with scribing visible. Established corner position \$85°W 21.1 ft. from bearing tree.

## Description of monument and accessories I established to perpetuate the original location of this corner

Set a 30 in. x  $2\frac{1}{2}$  in. iron pipe with 3 in. brass cap marked as shown, 26 in. in the ground, for the 1/4 Sec. Cor. between Sec 11 & 14, from which a new ST-

A pine 34 in. diam. bears \$16°E 45.1 ft. dist. marked TIS R36E 1/4 \$ 14.3T

Distance taken to a brass washer in the blaze of the tree. Set a steel fence post approximately 5 ft. East from corner with Forest Boundary sign attached.

Used steel tape and magnetic compass with declaration =  $20^{\circ}$  East.

TIS R 36E 1/4 S 11 1972 PLS 848

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON DOUGLAS M. FERGUSON 848

> > Office of County of County