USDA-FOREST SERVICE			
index File No. <u>J-19</u>	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Cor. No
T <u>1S</u> R. <u>36E</u>	R.D. Walla Walla County_	Umatilla	
Merid. Willamette	N.F. Umatilla State C	Oregon	
CORNER DIAGRAM T1S R36E	DESCRIBE CORNER MONUMENT FOUND $2\frac{1}{2}$ " iron pipe with 3" in diagram.		ed as shown
S.11 1/4———	See Certified Land Rec	cord no. H-158-R	•
N S14 1972 PLS 848	DESCRIBE BEARING TREES OR OTHER OF A 38" douglas fir bear declination 20°E)-21.1 A 26" ponderosa pine b	rs N83°E (N85°E feet, with hea Dears S17½°E-46.	with led blaze.
PHOTO IDENTIFICATION DATA Photo No. Filed At.	pitched over, with scr	ibing.	3
Object Ident. Ident. By Signature PLANE COORDINATE POSITION DATA	DESCRIBE CORNER LOCATION RELATIVE T Corner falls on wester Approximately 500 feet	ly slope in tim	ber.
State Zone XY	on Meacham Creek.		
Estob. By			4
Will: R. Wells	The state of the s	ANDLETON 7/22	FS-7100-52 (3/68) 5

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a steel fence post 5 feet East of monument with 54-2 and 54-9 signs attached.

A 16" douglas fir bears S49 3/4°E-26.1 feet, scribed: 1/4 S14 BT. A 16" douglas fir bears N7°W-49.0 feet, scribed: 1/4 S11 BT. New bearing trees have a brass washer stamped 'PLS 1106' nailed to the face of the blaze. Attached 54-3 and 54-9 signs, painted a 6" band and face of blaze red.

Work Done By. WR Wells Title PLS Date State Registration Na PLS 1106

Certified Cor. Record Prepared ? Yes X No Filed At: UMATILIA COUNTY SURVEYOR'S OFFICE Date 12/94

REMARKS

This corner was maintained as part of a USFS contract.

			<u> </u>				*	12
Index-File No.		T.		R.	M.	Tract or Surv. No.	Cor.	13
-	J19		18	36E	Wi	llamette		

Index	CORNER RECORD (SEARCH) Tract or J 19 Survey No.	
т <u>1 S</u> R. <u>36 E</u>	R.D. Pendleton County Umatilla	100
Merid. <u>Willamette</u>	N.F. <u>Umatilla</u> State <u>Oregon</u>	
CORNER DIAGRAM T1S R36E	DESCRIBE CORNER MONUMENT FOUND	
\$ 11	Set brass cap summer 1972. See reverse	side.
\$ 14	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
5) 14	Found 36" fir, live in good condition, vigible.	with scribing
PHOTO IDENTIFICATION DATA Photo No Filed At		
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO H	IOW TO REACH CORNER
Ident, By Signature		, <u>.</u>
PLANE COORDINATE POSITION DATA	Established corner postion S85°W 21.1 tree.	ft. from bearing
State Zone		
×		
Y		(FILME)
Estab. By	The Carlo Arthur Manager & Communication of the Com	10
Signature	Title Division Headquarters Date	7100-52 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a $30x2\frac{1}{2}$ " iron pipe with 3" brass cap marked as shown, 26" in ground, for the 1/4 section corner between sec. 11 & 14, from which a new BT:

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A pine 24" diam. bears S16°E. 45.1 ft. dist. marked T1S R36E 1/4 S14 BT. Distance taken to a brass washer in the blaze of the tree. Set a steel fence post approx. 5 ft. East from corner with Forest Poundary sign attached.

Used steel tape and magnetic compass with declination = 20° East.

Work Done By D.M. Ferguson Title Land Surveyor Date 7/12/6 State Registration No. 848

Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Courthouse Date 11/16/72 11

REMARKS

13

Cor,