USDA-FOREST SERVICE	$q \sim q \sim q$	
Index File No. <u>N-3</u>	CORNER RECORD (SEARCH) Tract or (Ref. FSM 7151.4) Survey No	NoN-3
T <u>1S</u> R. <u>36E</u>	R.D. Pendleton County Umatilla	
Merid. <u>Willamette</u>	N.F. Umatilla State Oregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
SEC.	None	
/9	X carved on p. pine on primitive N-S road. bearing west to ravine. Searched both side evidence.	Followed compass
PHOTO IDENTIFICATION DATA		
Photo No.		
Filed At.		_
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, AL	SO HOW TO REACH CORNER
Signature. 7		
PLANE COORDINATE POSITION DATA State Zone		
×		
Y		
Estab. By		
Signature		7100 52 (2 (20)
Bill Moore	Eng, Tech, 9/9	/100-52-(3/68)

,	Р	О	9	02	-6	7

CORNER RECORD (PERPETUATION)

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By Title	State Registration No. Date or Agency
Certified Cor. Record Prepared ? Yes No Filed At:	Date I

REMARKS

Index File No. T.

R.

M.

Tract or Surv. No.

Cor.

13