## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established this survey.

T 1 S R 36 E S1/16 S 20 S 21

Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the original location of this corner

Set a  $2\frac{1}{2}$ " brass cap on a 2" iron pipe 6" above the ground in earth and rock mound with a 6! steel fence post alongside with signs 54-4 and 54-3 attached.

New bearing trees:

A fir 7" diam bears N  $^{12}$ ° E., 12.4 ft dist marked S1/16 S 21 BT A fir 10" diam bears S  $^{14}$ °30' W., 4.5 ft dist marked S  $^{1/16}$  S 20 BT

Each BT has a sign 54-3 attached 6" below a band of red paint and has a brass washer marked RPE 2808 nailed flush with BT blaze.

Brass cap is marked:

T 1 S R 36 E S1/16

S 20 S 21

RPE2808 1976



Office ofSurveyor	County of Umatilla
for record on the 26 day of August.	rtify that the within instrument was filed in this affice.
(COUNTY OFFICIAL)	by

Q-12