R-25

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881 by

Surveyor General Records (notes) states:

Set post 4 ft. long, 4in. sq. 24 in. in ground on the West slope in dead and fallen timber, 300 ft. below the summit for the Cor to Secs. 19, 24, 25, and 30, marked TIS S19 on NE, R37E S30 on SE, R36E S25 on SW and S24 on the NW face with 2 notches on the South and 4 notches on the North edge from which:

Jacob C. Cooper under General Land Office Contract No. 397.

DIAGRAM	
T.15.	T.IS.
S. 24 S. 25	R.37E S.19
R.36E.	

A pine 40 in. diam. bears N800W 61 iks. dist. marked T1S R36E S24 BT.

A pine 36 in. diam. bears \$40°W 188 lks. dist. marked TIS R36E \$25 BT.

A pine 32 in. diam. bears S3°E 60 lks. dist. marked TIS R37E S30 BT.

Subsequent survey placed a set of corners for TIS R37E.

(No subsequent remonumentations in county records)

## Description of corner evidence found:

Found a 40 in. pine, live in good condition, with all scribing visible, bearing N20 W, 40.3 ft. dist. from the corner position.

Found a  $32^{11}$  pine down and rotten blaze and ax marks visible with scribing burnt out. Bearing  $83^{\circ}E$  39.5 ft. from the corner position.

Found a 36 in. pine snag (dead) with all scribing visible. Bearing S40 $^{\rm O}$ W 71.2 ft. from corner position.

Notes give 188 lks. distance; original surveyor apparently intended to give 108 lks. distance.

Compass bearing South intersects corner to Sec. 19 & 30, T1S, R37E.

## Description of monument and accessories I established to perpetuate the original location of this corner

Set a 30 in. x  $2\frac{1}{2}$  in. iron pipe with 3 in. brass cap marked as shown, 24 in. in the ground for the corner to Sec. 24 & 25, T1S R 36E, from which new BT's—A fir 14 in. diam. bears  $856^{\circ}$ E, 4.8 ft. dist. marked T1S R37E 819 BT.

A fir 14 in. diam. bears \$56°E, 4.0 ft. dist. marked 115 Ryke \$19 Bi.

A tamarack 16 in. diam. bears \$76°W 12.6 ft. dist. marked TIS R36E \$25 BT.

Distances taken to a brass washer in the blaze of each tree. Set a steel fence post approximately 5 ft. North from corner position with "Attention" sign attached.

Used steel tape and magnetic compass with declanation = 20° East.

PROFESSIONAL LAND SURVEYOR

> OREGON DOUGLAS M. FERGUSON 8 4 8

T.IS.

S.24
S.25
R.36E.

1972
PLS 848

Office of State of County of Additional State of County of County