USDA-FOREST SERVICE Index File No. S-6	CORNER RECORD (SEARCH) Tract or Cor. - Bendloten (Ref. FSM 7151.4) Survey No No
T 1S R. 36E Merid. Willamette	R.D. Pendleton County Umatilia No
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND N/A
N NW 1/16 829	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND N/A
PHOTO IDENTIFICATION DATA Photo No. Filed At. Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	From its junction with road #3102 follow spur 015 to its end. Corner is Northeast about 700 feet.
Signature Lowey W. Arahy	Title Division Headquarters Date 7100-52 (3, 68) Land Surveyor 10/82

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 21/2"x30" Gal. Iron pipe 14" in ground built mound of stone around monument.

ACCESSORIES | DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE 12" D-Fir N11E, 19.6 ft. scribed NW1/16S29BT

and with a 1" Brass disk stampedd PLS 896. 12" D-Fir N82E, 42.1 ft. scribed NW1/16S29BT and with a 1" Brass disk stamped PLS 896.

Work Done By Larry D. Bishop Title Surveyor Date 10/82 State Registration No. Certified Cor. Record Prepared ? Yes No X Filed At: Date REMARKS

Set guard posts North and East with signs 54-9 and 54-2.

Painted red band and bhazes red on BT's - nailed signs 54-9 and BT signs to BT's.

Index File No. R. Cor.

Tract or Surv. No.