USDA-FOREST SERVICE Index File No. S-7	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No		
T1S R.36E	R.DPendleton County _Umatilla		
Merid. Willamette.	N.F. Umatilla Stote Oregon		
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND		
_	N/A		
<i>k</i>			
N N1/16 1 g20			
N N1/16 S29	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND		
1	N/A		
	_6		
PHOTO IDENTIFICATION DATA			
Photo No.	<del>-</del>		
Filed At.	<u>-</u>		
Object IdentIdent. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER		
Signature	From its junction with road #3102 follow spur 020-0.8 mile to		
PLANE COORDINATE POSITION DATA	posted line. Corner is South approx. 500 feet/		
State Zone			
X	-		
Υ	<u> </u>		
Estab. By	<u> </u>		
	8		
Source J. Brilay	Title Division Headquarters Date 7100-52-(3/68)		
on o v. namay	Land Surveyor 10/82		

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 21/"x30" Gal. Iron pipe 24" in ground. No stones around.

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

16" Wh.Fir N13W, 8.0 ft. scribed CN1/16S29BT

and with a 1" Brass disk stamped PLS 896.

6" Wh.Fir N48W, 4.3 ft. scribed CN1/16S29BT

and with a 1" Brass disk stamped PLS 896.

		10
Work Done By Larry D. Bishop Title Surveyor	Dote 10/82 State Registration No. 896	_
Certified Cor. Record Prepared ? Yes No X Filed At:	Date	11
REMARI	(S	$\overline{}$

Set guard posts with signs 54-9 and 54-2 West and North, nailed signs 54-9 and BT signs to BT's. Painted red band and blazes red on BT's.

Index File No. T. R. M. Tract or Surv. No.

· Cor.