| USDA-FOREST SERVICE Index Z-11 File No. | CORNER RECORD (SEARCH) Tract or No. Z-11 |
|--|--|
| T <u>1S</u> R. <u>36E</u> | R.D. Pendleton County Umatilla & Union |
| Merid. <u>Willamette</u> | N.F. <u>Umatilla</u> State <u>Oregon</u> |
| CORNER DIAGRAM | DESCRIBE CORNER MONUMENT FOUND Material: Steel fence post. Height Above Ground: 3' Condition: Good Markings: BLM location poster wired to post - 2 stones at base, no visible marks. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 36" dia. p. pine stump - N 10 E - 12' dist. with BLM |
| PHOTO IDENTIFICATION DATA Photo No. Filed At. Object Ident. Ident. By Signature. | bearing tree poster on top. 30" dia. p. pine stump - S29E - 26' dist. 30" stump has BLM bearing tree poster nailed on top. N61W - 12' dist. from ½ cor. 18 8" p. pine with F.S. DI location poster and attention poster on it. Poster dated 5/16½73 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER |
| PLANE COORDINATE POSITION DATA State Zone X Y Estob. By | |
| Signature Bill Moore | Title Division Headquarters Date 7100-52 (3/68) Eng. Tech. 9/9/77 5 |

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By.______ Title______ Date_____ or Agency_____

Certified Cor. Record Prepared ? Yes No Filed At: Date

REMARKS

Index File No.

R.

M.

Tract or Surv. No.

Cor.

12