CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner orginally established by Henry Meldrum under GLO Contract No. 450, dated June 11, 1882. Surveyor General record states: Set post 4 ft long 4 in square, 24 in in ground for Cor to Secs 6 & 7, marked

T.1S. R 37 E on E

S 6 on N and

S 7 on S faces, with

5 notches on S and

1 notch on N edges, from which: A pine 12 in diam bears N 72° E 47 lks dist marked T.1.S. S 6. BT. A pine 10 in diam bears S 58° E 14 lks dist marked R.37.E. S 7. BT.

A fir 6 in diam bears N 73° W 24 lks dist marked R.36.E. BT.

Description of corner evidence found:

No remains of original corner found, re-established by single proportionate measurement, using U.S. Deputy Surveyor, Henry Meldrum's record, from GLO contract no. 450.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ " x 30" aluminum pipe - 25" in the ground with mound of earth to cap, marked as shown in corner diagram. Set steel fence post with signs 54-2 and 54-9 attached - 2.6 feet South of monument.

From which:

A 5/8" x 30" iron pin with yellow plastic cap bears N 44° E - 23.3 feet. A 5/8" x 30" iron pin with yellow plastic cap bears N 84 3/4° E - 15.9 feet. A 5/8" x 30" iron pin with yellow plastic cap bears S 68° E - 34.1 feet. A 5/8" x 30" iron pin with yellow plastic cap bears S 34° E - 23.4 feet. Attached sign 54-3 to iron pins, and sign 54-9 to steel fence posts set near iron pins.

I hereby certify that the above corner was properly monumented to U.S.F.S. standards by me on November 3, 1994.

Compass declination 18° East.

PROFESSIONAL LAND SURVEYOR R. Wells OREGON JULY 22, 19/7 WILLIAM R. WELLS 1106

REGISTERED

DIAGRAM

R36E

T1S

R37E

S7

S6

1994

1106

Office of Surveyor county of Umatilla 10 December 1994 HKlu by (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

*GPO-591-971, 1988