History of original corner establishment:

Set a 14"x8"x6" Basalt Stone 9" in the ground.

8" Fir MN7W 241ks. Mkd. R37E S17 BT 24" Pine N43E 14 1ks. Mkd. T1S S16 BT 30" Pine S67E 42 1ks. S21 BT 9" Fir S15W 72 1ks. Mkd. S20 BT DIAGRAM

T1S R37E S17 S16 S20 S21

11-9

Description of corner evidence found:

Mound of stones with old red flagging.

Fir snag S20W 40.0° (Scribing not visible)

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2"x30" Iron pipe with brass-cap marked:

T1S R37E S17 S16 S20 S21 1978 RLS 346

8" Fir S19E 78.9" Mkd. T1S R37E S21 BT 8" Fir N35E 67.6" Mkd. T1S R37E S16 BT 8" Pine N54W 119.4" Mkd. T1S R37E S17 BT 6" Pine S38W 150.1 Mkd. T1s R37E S20 BT

All BT's have a red painted stripe and BT signs. The new trees have a brass washer stamped RLS 346 nailed to the lower face. There are 2-6' steel fence-posts set on line apx. 5' from corner.

Form R6-7100-57 (9/71)

☆ GPO---798-276

PROFESSIONAL AND SURVEYOR

OREGON

346