

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla. DATE: 04/26/17.

CORNER DESIGNATION: G-3, The Center one-quarter corner of Section 7, Township 2 North, Range 28 East, W.M..

PREVIOUS RENEWALS/SURVEYS ETC: Corner has not been previously established.

MONUMENT AND ACCESSORIES FOUND: None.

CORNER IDENTIFICATION:

T2N R28E  
C1/4 + S7

MONUMENT SET: Corner established by survey. At the corner point, set a 5/8" by 30" rebar with 1 1/4" red plastic cap marked "ORPLS 1106 WAPLS 17372, 29" in the ground. The corner falls near the edge of an active wheat field.

New accessories:

- Top center of an existing monitoring well bears S 89°23' E, 353.6 feet.
- A 5/8" by 24" rebar with 1 1/4" red plastic cap bears N 28° E, 21.0 feet.
- A 5/8" by 24" rebar with 1 1/4" red plastic cap bears S 84° E, 24.2 feet.
- A 5/8" by 24" rebar with 1 1/4" red plastic cap bears S 45° E, 40.7 feet.

Red plastic caps on rebar accessories are marked "ORPLS 1106 WAPLS 17372". Set steel fence post 1 1/2 feet South of corner with "witness" sign wired to it. Wired "bearing object" signs to each rebar accessory.

LOCATION AND COMMENTS: Corner is West of a dirt field road near the Northeast corner of an active wheat field.

FIRM: Wells Surveying  
P.O. Box 1696  
Pendleton, OR 97801


COMPASS DECLINATION: 18° East

\2N28G3

Surveyor's Seal



*William R. Wells*



*renews 6-30-18*