### OREGON CORNER RESTORATION FORM

SECTION: 19 TOWNSHIP: 2N RANGE: 29E N-1

COUNTY: UMATILLA DATE: 6/2010

CORNER DESIGNATION

NW 19

CORNER DESIGNATION

NW 19

CONDITION REPORT ONLY

NOT FOUND

X RENEWED

UNRECORDED

SURVEYED IN

X REFERENCED OUT

#### PREVIOUS RENEWALS/SURVEYS ETC.


Originally surveyed by Thompson under Contract #83 in 1859. He set post and made mound. In 1980 Terry Hamby set a 2 ½" brass cap.

#### MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found Hamby's 2 1/2" brass cap.

# MONUMENT DETAIL

T2N R28E R29E 13 | 18 24 | 19 1980 PLS 1638



## OREGON STATE PLANE COORDINATES NORTH ZONE, NAD 83(91), Int Feet:

723966.16 8522146.92

#### MONUMENT SET (PROCEDURES AND DESCRIPTION)

# NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 78° 16' 05" E 19.48' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 18° 54' 18" E 52.31' A 5/8" x 30" Iron Rebar with plastic cap # 951 bears N 89° 27' 54" W 13.24' A 5/8" x 30" Iron Rebar with plastic cap # 951 bears S 4° 24' 34" E 331.13' These bearings and distances are State Plane.

#### LOCATION AND COMMENTS

From the intersection of Vey Road with Whitehouse Road go south along Whitehouse Road and along a dirt road 3 miles to corner. Corner lies on the east edge of a dirt road.

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: G. EDWARDS WITNESS: R. SMITH SURVEYOR'S SEAL

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/11

C:\Works\N5R29-J1

11-63-e.