CERTIFIED RECORD OF LAND CORNER MONUMENTATION

32E. , W.M.

History of original corner establishment:

This corner was originally established by D. Thompson, U.S. under Contract No. 106 dated August 16, 1864. The original at the corner a wood post was set with charred stake, earth

In 1904, John Kimbrell, in performing County Survey No. 212, regignal corner and remonumented it as follows: "The corner of the corner of the

This corner was remonumented by City crews in 1974 with the present brass cap monument.

Corner Code No. Note: Monument marked as shown below

DIAGRAM

CITY OF PENOLETON T3N R32E

> 531 | 532 S6 | S5

T2N R32E

Compass Declination: 18.0

Description of corner evidence found:

Found 2" brass cap set in concrete, flush with top of the asphalt on an abandoned road. The cap is marked as shown.

Description of monument and accessories I established to perpetuate the

original location of this corner:

The existing brass cap is solidly and permanently set so no new monument was installed. I added section, township and range markings on cap, and the cap is now marked as shown on the corner diagram. From the existing monument, reference monuments bear as follows:

A 1 1/2" yellow plastic cap marked "W.R. Wells PLS 1106", set on a 5/8" by 30" iron rod bears N69°E 42.90'.

A 1 1/2" aluminum cap, marked as shown , set on a 5/8" by 30" iron rod bears 869° W 23.88'.

A cross cut in the west side of the ring of an existing manhole is located 29.06' from the existing monument.

Set steel fence posts with witness corner and bearing object signs attached near each reference monument.

The aluminum cap on the reference monument is marked:

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 22, 1977 WILLIAM R. WELLS 1106



Office of	County of
	ify that the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	. by(DEPUTY)