## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

2N, R 32E.

History of original corner establishment:

This corner was originally established by David Chaplin, U.S. Deputy Surveyor, under Contract No. 107, dated August 21, 1864. The notes state that a 12 by 8 by 8 stone was set for the corner.

County Survey No. 11, surveyed in 1881, indicates that a stone in sound was recovered for this corner.

In 1887, under Special Instructions and Contract, Currin and Noland recovered the corner.

John Kimbrell's map on Page 310 of Record of Private Surveys Book No. 1, indicates that he may have incorrectly proportioned the corner in between the northeast and southeast corner of Section 2. The map does not show that Kimbrell established any corner monument.

More recent survey maps in the County Surveyor's Office show the corner point being reestablished by single proportion measure between the southeast and northeast corners of Section 2. The corner may reestablished and remonumented as shown on hap No. R-23-B, by PLS 16.88, in 1980.

Corner Code No. C-21 Note: Monument marked as shown below

DIAGRAM	
T	EN R32E
	1/4
52	!   S1
1	988 -
PLS	1106

Compass Declination: 18.0

## Description of corner evidence found:

Found a 14 by 10 by 8" basalt stone, firmly set in an east-west fence line about 3' east of a fence corner. The top of the stone was at ground level, and is plainly marked "1/4" on the top of the stone. Fences go north, south and east from the fence corner.

This stone is believed to be the original corner stone, established under Contract No. 107.

The monument by PLS 1638 bears N6 W°26.75' from the found corner stone.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position of the found corner stone, I set a 2 1/2" brass cap on a 1 1/2" by 30" galv. iron pipe, 20" in the ground and surrounded with a mound of earth and stone. Buried the corner stone in the new mound. During excavation for the new monument, it was discovered that the corner stone is surrounded with a mound of stone, below ground. Referenced the new monument as follows. From the new monument:

The 2 1/2" brass cap on iron pipe monument by PLS 1638 bears  $N6^\circ W$  26.75'. Attached witness corner and bearing object signs to a steel fence post set near this reference monument.

An aluminum nail in the southwest side of PP&L Pole No. 029460 bears S69°E 11.91'. Attached witness corner and bearing object signs to the pole.

Note: The monument by PLS 1638 is marked as follows:

T2N R32E 1/4 S2 | S1 1980 PLS 1638

REGISTERED PROFESSIONAL LAND SURVEYOR lli R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS

1106

Office of	. County of
State of I hereby certify the	hat the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)