CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 2N, R 32E., W.M.

History of original corner establishment:

This corner had been established and or re-established several times, in various surveys, prior to 1917.

In 1917, L.E. Wilkes, under Group 29 Instructions, recovered a 10 % 5 % 4 inch stone, marked 1/4 on West side and DR on East side and remonumented it. Wilkes remonumented the corner with a witness corner monument, a 3 long by 2 diameter iron post, set 1/2 link South of the corner point.

Corner Code No. 6-25
Note: Nonment narked as shown below
DIAGRAM
N.C.

Corper No. Compass Declination: 18.0

PLS 1106

Description of corner evidence found:

None. The corner area has been destroyed by a road cut.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. WELLS

Willin R. Wells

Description of monument and accessories I established to perpetuate the original location of this corner:

The corner was re-established by broken boundary methods as shown in the 1973 "Manual of Instructions", between the recovered West 1/4 corner and South 1 1/6 th corner of Section 7, T2N R33E, W.M..

Since corner point falls in a highway shoulder subject to construction, at a point S $00^{\circ}\,02'10''$ E 60.00' from true corner point I establish a witness corner monument.

The witness corner is a 2 1/2" brass cap, marked as shown in corner diagram, set on a 1 1/4" by 30" galvanized iron pipe. The monument is set 24" in the ground and surrounded with a mound of earth and stone.

Reference the witness corner monument as follows:

The 1/4 corner monument on the West boundary of Section 7, T2N R33E, W.M. bears N 00° 13′49″E 259.45′. A concrete nail with brass washer, 1′ East of the West edge of the pavement of the highway bears N 8 1/2°E 59.0′. The brass washer is stamped "PLS 1106″. A brass washer nailed to the South side of post for "Slower Traffic Keep Right" sign bears S 48 1/2°E 30.4′. The brass washer is stamped "PLS 1106″ and is 5.5′ above ground on the post. A brass washer, 5.5′ above ground, in PP&L Pole No. 129401, bears N 65°W 82.9′. The brass washer is stamped "PLS 1106″. Attached bearing object sign to the pole.

Set steel fence post 3' South of corner and attached witness corner sign.

Office of autry DEAL County of Urnatell & State of County of Urnatell & County of Urnatell &

Form R6-7100-57 (9/71)

RECEIV CLIPY

☆GPO: 1989-692-049

No. 90-50