## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 2N, R 32E., W.M.

History of original corner establishment:

This corner was originally established by Daniel Chaplin, U.S. Deputy Surveyor, under Contract No. 107, dated September 21, 1864.

I.F. Moody, U.S. Deputy Surveyor, in Contract No. 164, dated October 4, 1871, established a new corner. The Moody corner superceded the corner established by Daniel Chaplin.

Currin and Noland, U.S. Deputy Surveyors, under Special Contract dated hay 1, 1887, failed to recover moody's corner and re-established the corner based on moody's survey.

In 1968, as shown on County Survey No. E-29-8, LS 346 determined the best remaining evidence of the torner was an existing fence corner and remonumented the corner point with a brass capped iron pipe.

Since 1968, the remonumented corner has been used on all surveys in the area.

Corner Code No. J-19 Note: Monument marked as shown below

DIAGRAM

11
14
12N R32E
RLS 346

Corper No. Compass Declination: 18.0

Description of corner evidence found:

Found 2 1/2" brass cap on a 1 1/4" galvanized iron pipe, set flush with the ground in an East-West fenceline. The cap is marked as shown in the corner diagram.

Description of monument and accessories I established to perpetuate the original location of this corner:

Reference the existing monument as follows:

A steel fence post, with witness corner and bearing object signs attached bears East 5.0'.

A 5/8" by 30" iron pin bears West 18.78'. Set steel fence post near reference monument and attached bearing object sign.

A 5/8" by 30" iron pin bears South 19.30'. Set steel fence post near reference monument and attached bearing object sign.

A brass washer, stamped "PLS 1106", nailed to the South side of PP&L Pole No. 114001, 1' above ground bears S 86°W 102.4'.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of	County of
State of / hereby certify th	
for record on the day of	
by	
(COUNTY OFFICIAL)	(DEPUTY)