T 2N, R 32E. . W.M.

History of original corner establishment:

Most recent approved 6LO record, by Currin and Noland, under Special Contract dated May 4, 1887, states:

"Found old mound and pits restored corner by setting a basalt stone 12x7x6 ins. 8 ins. in the ground marked with 3 notches on South and 2 notches on the East edges, redug pits and raised a mound of earth 2 tt. high & 4 1/2 ft. base around it.

Note: We find no record of the establishment of the found brass cap monument by the City of Pendleton. The brass cap monument is believed to be a perpetuation of the hub set for the corner point by Charles Eddleman, burning his survey in January, 1956. (City Map Record No. 24-7509).

Corner designation: T2N R32E

S15 | S14 S22 | S23 Corner Code No. N-17 Note: Monument marked as shown below

DIAGRAM

CITY OF

PENDLETON

Corner No. Compass Declination: 18.0°

Description of corner evidence found:

Found a 1 3/4" brass cap set in concrete 1.4' South of a East-West fence and 6" below ground surface.

Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained by cleaning up around found monument.
Referenced the existing monument with the following accessories:

A 5/8" by 30" iron pin bears N 81° W - 16.55'. A 5/8" by 30" iron pin bears N 76 1/2°E - 16.25'. A 5/8" by 30" iron pin bears N 88°E - 20.23'. A 5/8" by 30" iron pin bears S 84 1/2°W - 14.54'.

All iron pins are capped with a yellow plastic cap marked "W.R WELLS, PLS 1106" Set steel fence posts approx. 1' from each pin and attached Bearing Object

Set a steel fence post 2' North of monument and attached a Witness Corner sign.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 19/7 WILLIAM R. WELLS 1106

4. Wells

RECEIVED BY

Form R6-7100-57 (9/71)

Umaiilla County Surveyor

# GPO-798-276

Rec'd By KC No. 92-92-C