

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 4/14/94

CORNER DESIGNATION: T-21. East 1/4 corner Section 26, T2N., R32E., W.M.

PREVIOUS RENEWALS/SURVEYS, ETC.: Most recent official GLO Survey was made by James P. Currin and James Noland, under Special Contract dated May 4, 1887. They set a stone 7 x 8 x 9 ins., 6 inches in the ground for 1/4 Sec. corner; marked 1/4 on West face; dug pits 18 x 18 x 12 inches N & S from stone, 5 1/2 ft. distant and raised a mound of earth 1 1/2 ft. high, 3 ft. base alongside.

MONUMENT AND ACCESSORIES FOUND: None.

MONUMENT MARKING DETAIL:

T2N R32E
1/4
S26 † S25
1994
PLS 1106

MONUMENT SET: Re-established corner position by single proportion measurement between the Northeast and Southeast corners of Section 26, and set a 2 1/2" brass cap on a 1 1/4" x 30" galvanized iron pipe, 46" in the ground, (marked as shown in the monument detail).

New Accessories:

A 5/8 x 30" iron pin with yellow plastic cap stamped "OR PLS 1106-WA PLS 17372" bears N 32° E-24.8 feet.

A 5/8 x 30" iron pin with yellow plastic cap stamped "OR PLS 1106-WA PLS 17372" bears S 20° E-39.0 feet.

A 5/8" x 30" iron pin with yellow plastic cap stamped "OR PLS 1106-WA PLS 17372" bears S 51° W-18.9 feet, top buried 1.2 feet below ground.

A 5/8" x 30" iron pin with yellow plastic cap stamped "OR PLS 1106-WA PLS 17372" bears N 32° W-21.9 feet, top buried 1.2 feet below ground.

Attached bearing object sign to each iron pin. Attached witness sign to wooden posts near the Northeast and Southeast reference monuments.

LOCATION & COMMENTS: Corner falls in farmed Conservation Reserve Program field.

COMPASS DECLINATION: 18° East.

Surveyor's Seal

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

Party Chief: Robert D. English

Notes: Robert D. English

Witness: F. Scot Munro

