PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/20/01

CORNER DESIGNATION: 2N33, C-1, The West 1/4 Corner of Section 6 only.

PREVIOUS RENEWALS/ SURVEYS, ETC ..:

Corner was recovered and remonumented in 1917 survey by L.E. Wilkes, on the West Boundary of the Diminished Reservation Boundary. in 1917. The True Corner is a 12" x 10" top dimension basalt stone marked N W COR RES on East face. This stone was established by Currin and Noland under Contract dated May 4th, 1887. Wilkes Witness Corner monument 1 lk (0.66') South of the Corner stone was remonumented per Corner Record No. 88-19-C recorded in the Umatilla County Surveyor's Office.

MONUMENT AND ACCESSORIES FOUND:

Found corner stone of record and a 2 1/2" brass cap on iron pipe witness monument buried 20" below ground, marked as shown in Monument Marking Detail. Per record Corner Record, accessories are intact. The corner has 2 accessories.

MONUMENT MARKING DETAIL:

LOCATION & COMMENTS:

This corner is located in a farmed field.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

For True Corner: N = 739759.34E = 8650514.91

For witness monument 0.66' S. N = 739758.68

E = 8650514.92

FIRM/AGENCY:

William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N33C1

HUCLIVED DI

Umatilla County Described

Data 12-01

01-211-9

Willi R. Wells

OREGOR

JOHN JOHN J. WELLS

REGISTERED

PROFESSIONAL

Venews 6-30-02