

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 03/06/02

CORNER DESIGNATION: 2N33Z11, The South 1/4 Corner of Section 33.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent Umatilla County Surveyors recorded corner record: 98-233-B.

MONUMENT AND ACCESSORIES FOUND: Found a 2 1/2" brass cap on a 2" galvanized iron pipe, 10" above ground level, marked as shown in monument marking detail. Monument is leaning slightly North. No visible accessories.

MONUMENT MARKING DETAIL:

INDIAN ALLOTMENT

T2N
1 S33
4 S4
WC 27 FT. S.
T1N R33E
1920

LOCATION & COMMENTS:

Corner is located on West side of a gravel drive off of Best Road, approximately 10 feet North of PP & L pole #044901.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

Witness Corner Position:	True Corner position 27.0 feet North:
N = 710687.60	N = 710714.59
E = 8664216.84	E = 8664216.05

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33Z11

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6/30/02

RECEIVED BY

Umatilla County Surveyor

Date 5-02

Rec'd By KK

No. 02-127-9