CERTIFIED RECORD OF LAND CORNER MONUMENTATION

L - 25 DIAGRAM

History of original corner establishment:

The original corner was established on October 21, 1871, by George S. Pershin and George Williams under their joint GLO contract No.154, as follows:

Set stone, 16" x 8" x 6" for the 1/4 section corner.

T2S 1/4 R R 3 S13|S14 3 0 LS 1636 0 E 2000 1/2 E

Original corner evidence recovered:

Found the original corner stone loosely set in a mound of stones. The corner stone is 18" x 12" x 10" and is plainly marked "1/4" on one face.

Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 30" flared, galvanized iron pipe 22" into the ground to bed rock. A 2 1/2" brass cap attached to the pipe is marked as shown in the diagram above. I bury the corner stone to the south of the pipe and build a mound of stones around the pipe, from which:

A 5/8 x 36" iron rod, set 35" into the ground with a 3/4" brass washer attached at ground level, marked "PLS 1636 NE", bears N32°E, 119.8 Feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer attached at ground level, marked "PLS 1636 SE", bears S13° 30'E, 187.0 feet.

A 5/8" x 24" iron rod, set 22" into the ground with a 3/4" brass washer attached at ground level, marked "PLS 1636 SW", bears S78°W, 154.5 feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer attached at ground level, marked "PLS 1636 NW", bears N36°W, 69.6 feet.

A 5 foot steel fence post with a "Witness Post" sign attached bears South, 1.0 foot.

I hereby certify the above corner point was perpetuated as hereon described on June 11, 2000. Magnetic declination set in compass: 18°E.

> OREGON DENNIS L

REGISTERED ROFESSIONA AND SUR

Renews June 30, 2001

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

Ussetilla Cousty Surreyo