## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

N - 9 DIAGRAM T2S R30E | S17|S16 S20|S21 | PLS 1636 | 2002

## History of original corner establishment:

The original corner was established by George S. Pershin on September 7, 1878, under GLO contract No. 293, as follows:

Set a stone, 12" x 10" x 8", for corner to sections 16, 17, 20 and 21. Dug pits and drove a willow stake as per instructions

## Original corner evidence recovered:

Found the original corner stone loosely set in a mound of stones. The corner stone is 13" x 10" x 8" and is plainly marked with four notches on one (east) edge and three notches on another (north) edge. The stake and pits of record are gone.

## Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 30" flared, galvanized iron pipe 27" into the ground. A 2 1/2" brass cap attached to the iron pipe is marked as shown in the diagram above. I bury the corner stone along the east side of the pipe and build a mound of stones around the pipe, from which:

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 16", attached at ground level, bears N29° E, 106.3 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 21", attached at ground level, bears S24° 30' E, 133.9 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 20", attached at ground level, bears S4° 30' W, 131.1 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 17", attached at ground level, bears N60° W, 109.8 feet.

The two reference monuments to the south are south of a gully.

I nail a "witness post" sign to a wooden fence post one foot southwest of the corner.

I hereby certify the above corner point was perpetuated as hereon described on February 6, 2002. Magnetic declination set in compass: 16° E.

PROFESSIONAL LAND SURVEYOR

DENNIS L. GAYLORD

Renews June 30, 2003

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY Umatilla County Surveyor