## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

	R - 19 DIAGRAM	
	1	-
History of original corner establishment:	T2S R30E	1
	1/4 <u>S23</u>	1
The original corner was established by George S. Pershin on	S26	1
September 4, 1878, under GLO contract No. 293, as follows:	PLS 1636	1
	2002	i
Set a stone, 14" x 12" x 5", on ridge for the 1/4 section corner.	I	j

## Original corner evidence recovered:

Found the original corner stone firmly set 10" in the ground on the west edge of a mound of stones. The corner stone is 17" x 16" x 7" and is plainly marked "1/4" on the north face.

## Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a  $1" \times 30"$  flared, galvanized iron pipe 20" into the ground to bedrock. A 2~1/2" brass cap attached to the top of the iron pipe is marked as shown in the diagram above. I bury the corner stone along the south side of the pipe and build a mound of stones around the pipe, from which:

A 5/8" x 24" iron rod, set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N50° E, 145.7 feet.

A 5/8" x 24" iron rod, set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S53° E, 119.5 feet,

A 5/8" x 24" iron rod, set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S44° W, 136.6 feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N46° 30' W, 110.0 feet.

I hereby certify the above corner point was perpetuated as hereon described on March 20, 2002. Magnetic declination set in compass: 18°E.

MAND SURVEYOR

PROFESSIONA

DENNIS L. GAYLORD

Renews June 30, 2003

Recorded at the office of County surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY

Umatilla County Surveyor

Date 6-02

Rec'd By K