## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

T2S R30E

1/4

The original corner was established by George S. Pershin on
S33|S34

September 5, 1878, under GLO contract No. 293, as follows:
PLS 1636
2002

Set a stone, 14" x 12" x 8", on north hillside for 1/4 section corner.

## Original corner evidence recovered:

Found the original corner stone solidly set 10" in the ground. The corner stone is 16" x 11" x 8" and is plainly marked "1/4" on the east face.

## Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 30" flared, galvanized iron pipe 27" into the ground. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the diagram above. I bury the corner stone along the south side of the pipe and build a small mound of stones around the pipe, from which:

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N52° E, 66.8 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S28° 30' E, 105.9 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S55° 30' W, 100.6 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N44° W, 96.3 feet.

I hereby certify this corner point was perpetuated as hereon described on February 5, 2002. Magnetic declination set in compass: 16° E.

PROFESSIONAL LAND SURVEYOR

OREGON JULY 14-1978 DENNIS L. GAYLORD

Renews June 30, 2003

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

RECAVED BY

Umatilla County Survey

Date 02-02

Reo'd by XX Ro. 02-40-R