CERTIFIED RECORD OF LAND CORNER MONUMENTATION

J - 9 DIAGRAM

History of original corner establishment:

The original corner was established by Daniel Chaplin on November 21, 1864, under GLO contract No. 107, as follows:

Set stone for corner to sections 8, 9, 16 & 17. (The size of the stone is not given in the original field notes).

T2S R31E <u>88|S9</u> S17|S16 PLS 1636 1998

Corner evidence recovered:

The original corner stone is loosely set in a small mound of stones. The corner stone is 14" x 11" x 10" and is plainly marked with four notches on the east edge and two notches on the north edge.

Monument and accessories established to perpetuate the original location of this corner:

In place of the original corner stone, I set a 1" \times 30" iron pipe, 28" into the ground. A 2 1/2" brass cap attached to the pipe is marked as shown in the diagram above. I bury the corner stone along the south side of the pipe and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S9", attached at ground level bears N74°30'E, 98.3 feet. A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S16", attached at ground level bears S43°30'E, 87.7 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S17", attached at ground level bears S55°W, 104.9 feet. This reference is southwest of a small draw.

A 5/8" x 36" iron rod set 34" into the ground with a 3/4" brass washer, marked "PLS 1636 S8", attached at ground level bears N58°30'W, 130.7 feet.

I hereby certify the above corner point was perpetuated as hereon described on April 16, 1998. Magnetic declination: 18 E.

PROFESSIONAL LAND SURVEYOR

OREGON /

DENNIS L. GAYLORD

Renews June 30, 1999.

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on ______, 1998.

RECEIVED BY

Umatilla County Surveyor

Rec'd By

No. 28-