History of original corner establishment:

The original corner was established by Daniel Chaplin on November 19, 1864, under GLO contract No. 107, as follows:

Set a stone 18" x 12" x 4" for the 1/4 section corner.

DIAGRAM

T2S R31E 1/4 <u>S23</u> S26 PLS 1636 1997

Description of corner evidence found:

The original corner stone is loosely set in an old fence corner. Fences project north and east. The stone is $18" \times 11" \times 5"$ and plainly marked "1/4".

Description of monument and accessories I established to perpetuate the original location of this corner:

In the spot occupied by the original corner stone, I set a 1 1/2" x 30" iron pipe, 25" into the ground. A 2 1/2" brass cap attached is marked as shown in the diagram above. I bury the corner stone along the south side of the pipe and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S23 NE", attached at ground level, bears N31°E, 23.1 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S26 SE", attached at ground level, bears S25°E, 120.0 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S26 SW", attached at ground level, bears S11°W, 66.5 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 S23 NW", attached at ground level, bears N31°W, 35.8 feet.

I hereby certify the above corner point was perpetuated as hereon described on February 17, 1997. Magnetic declination: 20°E.

Office of COUNTY SURVEYOR County of UMATILLA DENNIS L. GAYLORD
State of OREGON, I hereby certify that the within instrument was filed in this office of 6/30/97

Laura II (COUNTY OFFICIAL)

PROFESSIONAL LAND SURVEYOR

OREGON

OREGON

DENNIS L. GAYLORD

1636

COUNTY OFFICIAL)

OPPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

REGISTERED

Umatilla County Surveyor

Rec'd By XX No. 91-25-8