CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Z - 5 DIAGRAM

History of original corner establishment:

The original corner was established by David P. Thompson on October 4, 1864, under GLO contract No. 106, as follows:

Set stone 22" x 12" x 4" for corner to sections 31, 32, 5 and 6.

T2S R31E <u>S31 | S32</u> S6 | S5 T3S PLS 1636 1998

Corner evidence recovered:

The original corner stone is loosely set in a large mound of stones. The corner stone is broken into several pieces, and I can see faint chisel marks on one face. I fit the pieces together and the stone is 19" x 12" x 5" in size.

Monument and accessories established to perpetuate the original location of this corner:

In place of the original corner stone, I set a 1" x 30" iron pipe, 12" into the ground to bedrock. A 2 1/2" brass cap attached is marked as shown in the diagram above. I bury the corner stone pieces to the north of the pipe and build a mound of stones around the pipe and over the brass cap, from which:

A 5/8" x 24" iron rod set 20" into the ground with a 3/4" brass washer, marked "PLS 1636 S32", attached at ground level, bears N47 9 45'E, 85.4 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 S5", attached at ground level, bears $S45^{\circ}E$, 106.6 feet. A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 S6", attached at ground level, bears $S26^{\circ}30$ 'W, 91.8 feet.

A 5/8" x 36" iron rod set 32" into the ground with a 3/4" brass washer, marked "PLS 1636 S31", attached at ground level, bears N40 $^{\rm o}$ 30'W, 103.4 feet.

I hereby certify the above corner point was perpetuated as hereon described on May 10, 1998. Magnetic declination: 18°E.

PROFESSIONAL LAND SURVEYOR

OREGON JULY 14 1978 DENNIS L. GAYLORD

Renews June 30, 1999

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on _______, 1998.

RECEIVED BY

Umatilla County Surveyor

Rec'd By

No. 98-112