USDA-FOREST SERVICE		
Index File No. Z-5	CORNER RECORD (SEARCH) Tract or (Ref. FSM 7151.4) Survey No	Cor. Closing
T <u>2S</u> R. <u>33E</u>	R.D. Ukiah County Umatilla	NoNo
Merid. <u>Willamette</u>	N.F. Umatilla State Oregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
$ \begin{array}{c} \frac{A \text{ M}}{CC} \\ S31 \\ \end{array} $	At corner position found mound of stone 1'x3' dia find original stone. This corner was set by a Ju closing corner. It does not fall on true line, s $\frac{A\ M}{m}$ for amended cor. and the true intersection pomented.	nior Survey as a
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	<u>2</u>
	Found a Douglas Fir 31" dia. for N.E. BT with vis "R33E". The dist. to the old BT from the center mound is $48.8 \text{ ft} = 74 \text{ lks}$.	ible scribing of the stone
PHOTO IDENTIFICATION DATA		
Photo No		
Filed At.		
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOL	3
Ident. By	Corner falls on stoop North slope at anything	N TO REACH CORNER
Signature 7	Corner falls on steep North slope at south edge of	fclearing
PLANE COORDINATE POSITION DATA	approximately 550' south of old Jeep Road on North	n side of
State Zone	- I GI GH &	
X		
Υ		
Estab. By		
House & signature	Title Division Headquarters Date ORLS 1294 9/77	7100-52-(3, 68)
	2/1/	5

CORNER RECORD (PERPETUATION)	АМ
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	ÇC .
At center of stone mound, set 2½"x30" galvanized pipe with brass cap stamped:	T2S R33E S31 S32
Set pipe 20" in ground with mound of stone to cap.	S3 T3S
ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE E	1980 OR PLS 1294

Live Doug. Fir 31" dia. bears N70°E, 48.8 ft. with open blaze and visible scribing "R33E".

New Trees: A Doug. Fir 12" dia. bears N39°W, 48.0 ft., scribed T2S R33E S31 cc BT. Attached 54-3 and 54-4 signs to all BTs. Attached brass washer stamped LS 1294 to foot blaze of new BTs. Painted blazes and 6" band around all BTs. Attached 54-4 sign to metal post 5' west of corner.

			10
Work Done By R.C. Orton		te <u>6/30/80</u> State Registration No.	
Certified Cor. Record Prepared ? Yes	X No Filed At:	Date	
Witnesses: R. Orton	REMARKS		

R. Orton

L. Huntsman D. Allen

Index File No. T. R. **Z-5**

33E

Tract or Surv. No.

Cor.

CORNER DIAGRAM TRUE CC	DESCRIBE CORNER MONUMENT FOUND At corner position found mound of stone l'x3' dia. Could not find original stone. The dist. to the old
S31 S32	BT from the center of the stone mound is 48.8 ft=74 lks. This original corner position does not fall at the true intersection point. The original corner position was monumented and 7100-\$7 made for it and stamped AM for amended corner. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND Found Douglas Fir 31" dia. for N.E. BT with visible scribing "R33E".
PHOTO IDENTIFICATION DATA Photo No. Filed At. Object Ident. Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER The corner falls on a steam county of the corner falls on a steam county of the corner falls.
PLANE COORDINATE POSITION DATA State Zone X Y Estab. By Signature Signature 8	The corner falls on a steep south slope at the edge of a clearing. Title Division Headquarters Date 7100-52 (3/68) ORLS 1294 9-77

CORNER RECORD (PERPETUATION) MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT T2S R33 E At True intersection point set 2 1/2"x30" galvanized pipe \$32 with brass cap stamped: \$31 **S**3 Set pipe 20" in ground with mound of stone to cap. T3S R33 E 1980 OR PLS 1294 ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Bearing Trees: Old: \check{A} Doug. Fir 31" dia. bears N60 $^{\circ}$ E 52.4 ft, scribed T2S R33E S32 CC BT. New: A Doug. Fir 12" dia. bear. N25°W 68.3 ft, scribed T2S R33E S31 CC BT. Attached 54-3 & 54-4 signs to all BT's. Attached brass washer stamped LS1294 to foot blaze of new BT's. Painted blazes and 6" band around all BT's. The 54-3 signs have True marked on them. Attached 54-2 & 54-4 signs to metal post 5' west of corner. Party Chief Date 8-18-80 State Registration No. Work Done By. R. C. Orton Title ____ Certified Cor. Record Prepared ? (Yes) No Filed At: Date REMARKS

Witnesses: R. Orton G. Wagoner

G. Lester

J. Anderson

Index File No. T. R. M. Tract or Surv. No. Cor. 13
7-5 25 33E

BW-14 1 Index 7 5 5 7 25 8 33 5	_ Su	act-or rvey No	Cor. Z - 5 6 No. Z - 5
	R.D. <u>Ukiah</u> County <u>Umaf</u> N.F. <u>Umafilla</u> State <u>Orego</u>		
Merid. Will.	DESCRIBE CORNER MONUMENT FOUND	<u> </u>	<u> </u>
COMMEN DIAGNAM	None		•
31			2
	DESCRIBE BEARING TREES OR OTHER OFFICIAL AC	CESSORIES FOUND	
	Mound of stone I high, I'm	L' diameter,	
	Mound of stone 1' high, 1's Fin BT- 30" DBH - N 80 E Visible scribing.	74 IKs, "I	(33 E" 15
	6 Visible scribing,	tree dying as	top is broken.
PHOTO IDENTIFICATION DATA		•	
Photo No.		v. v. v. v	
Filed AtObject ident	- OCCODER CODMED LOCATION BELATIVE TO MEAR	DV EEATURED ALOO U	3
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-	BT FEATURES, ALSO HE	JW TO REACH CORNER
Signature	7		
PLANE COORDINATE POSITION DATA		·	
State Zone			
X	-		
Estab. By	- - - 8		4
Mike Livy	Title Division Headquarters Eng. Aide USFS Umatilla	-5.0. 8-4-69	7100-52 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Put BT tag (54-3) and aftention tag (54-4) on BT,

Painted red ving around tree and "BT" on it.

Painted mound and a staub stuck in mound,

	· · · · · · · · · · · · · · · · · · ·				10
Work Done	By Mike Lilly	Title ENGY Ride	Date 8	State Registration No. US FORESP SERVITO	E
Certified C	or. Record Prepared ? Yes	No Filed At:		Date	
	Found cont 35, R33 E.	nen by pacing	E. 8.5ch.,	from NW con. Sec 3,	

12

2S R. 33E M. W111, Tract or Surv. No.

Index File No.7-5