DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
PHOTO IDENTIFICATION DATA Photo No Filed At.	

## CORNER RECORD (PERPETUATION)

## MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Found 2" iron pipe with brass cap marked; Cap straight but loose, Firmed up with 6x36 inch mound of earth and mound of stone

67M 1917

T2S R34E

UIR

around to cap. Cap 20" above ground.

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE From which by magnetic declination of N20°E: A down and rotten pine bears

N45°E, 56.6 ft. A 24" fir bears N62°E, 78.1 ft with grown over blazes. A 40" fir bears S61°E, 15.4 ft. with grown over blazes. Painted 6" red bands around. Two good BTs. Placed 54-3s, and 54-4s Placed 54-2 and 54-4 on steel fence post 5' east of the corner. No trace of 20" fir, N23°W, 58 links.

Work Done By B. B. Barbour Title P.L.S. Dote 11-6-80 State Registration No. OR 1051
Certified Cor. Record Prepared ? Yes X No Filed At: Union County Surveyor's Date !!
DEMARKS THE PROPERTY OF THE PR

Daniel Rowland Witnesses: Doug Moser

Ron Gilrov

Index File No. Τ. R.

Tract or Surv. No.

Cor.