CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original comer establishment:

This corner was originally established by Jacob Cooper under G.L.O. contract no. 397 dated July 1, 1881. He set a post 4' long and 4" square 2' in the ground. From which:

A Fir, 40" dia., S79°E, 44 lks. A Tamarack, 15" dia., N4°E, 58 lks. No other trees were in limits.

Corner was found by L.E. Wilkes, U.S. Surveyor, during his resurvey in 1917. He found the post and his record states, 4 BTs, the one in S19 being dead and down. At the corner he set a 2"x3" iron pipe with a brass cap marked:

(Continued on page 2 of 2)

Description of corner evidence found:

Found iron pipe and brass cap as described by Wilkes. From which:

A Tamarack, dead, 26" dia., N6°E, 84.4 ft. with scribing visible.

A D. Fir, 17" dia., N28 3/4°E, 22.5 ft. with healed blaze.

A D. Fir snag, 36" dia., S78 3/4°E, 28.6 ft. with scribing visible.

A D. Fir, dead, 32" dia., S71½°W, 71.8 ft. with healed blaze.

A D. Fir, 22" dia., N13½°W, 91.8 ft. with healed blaze.

Page 1 of 2

DIAGRAM

T2S R34E R35E S24 S19 S25 S30

R-25

T2S R34E R35E S24 S19 S25 S30 1917

Description of monument and accessories I established to perpetuate the original location of this corner:

Mark new BTs:

A D. Fir, 21" dia., S40°W, 99.0 ft. marked: T2S R34E S25 BT A Tamarack, 18" dia., S30°E, 39.8 ft. marked: T2S R35E S30 BT

BTs have blaze and a 6" stripe painted red, a BT tag and an "Attention" sign. New BTs have, additionally, an alum. "PLS 1832" washer nailed to the bottom of the blaze. There is a 6' steel fence post with an "Attention" sign within 5' of the corner.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at 1850E.

September 2, 1984

REGISTERED PROFESSIONAL LAND SURVEYOR

FAYETTE S. MUNRO

Office of DURUELADR County of Umatila State of ... ORCGO I hereby certify that the within instrument was filed in this office for record on the .. 70. day of .. October 1984 David H. Krumbein by (DEPUTY)

Form R6-7100-57 (9/71)

GPO--798-276

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original comer establishment:

From which:

A Fir, 8" dia., N28° 30'E, 36 lks. (New BT) A Fir, 40" dia., S79°E, 44 lks. (Old BT) A Fir, 24" dia., S68°W, 108 lks. (Old BT) A Fir, 10" dia., N12°W, 141 lks. (Old BT) Page 2 of 2

DIAGRAM

T2S

R34E R35E

S24 S19

S25 S30

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Sayette Munro

OREGON
JULY 13, 1979

FAYETTE S. MUNRO
1832

Office of SUPPRIAR	county of Umatilla
Onto on the second seco	County or
State of CR.C.O I hereby cert	ify that the within instrument was filed in this office
for record on the 10 day of Octol	XER. 1984
David H KRUMROID	ify that the within instrument was filed in this office
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

GPO-798-276