23


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1882 by Herman D. Gradon, under General Land Office Contract No. 452.

Surveyor General Records (Notes) states:

Pine post 4' long 3" thick 2' in ground from which a
pine 15" dia. bears N14°E 138 lks. dist.

A fir 20" dia. bears S14°W 75 lks.



(No subsequent remonumentations in county records)

Description of corner evidence found:

Found 24 in. ponderosa pine, live in good condition, marked 1/4 S, positioned 1/4 corner between Section 35 and 2, S14°W, 91 ft. dist. from notch in blaze.

Description of monument and accessories I established to perpotuate the original location of this corner

Set 30 in. \times $2\frac{1}{2}$ in. Iron pipe with 3 in. brass cap marked as shown 6 in. in the ground to solid rock and chiseled an "X" in rock under pipe for the 1/4 Section Corner between Sections 35 & 4, and raised a wound of stone 4 ft. in

diam. and $2\frac{1}{2}$ ft. high around the pipe, from which new BT's - A 20 in. fir bears S60°W 86.9 ft. marked T2S R36E 1/4 S2 BT. Measurement taken to a brass washer in face of blaze. Set steel fence post approximately 5 ft. west with warning sign attached.

Used steel tape and magnetic compass with declanation = 20° East.

TIS R36E 1/4 - S 35 S 2 T 2 S 1 9 7 2 PLS 848

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON DOUGLAS M. FERGUSON 848

Office of State of Country of Cou

Form R6-7100-57 (9/66)

H-157