

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla. DATE: 03/06/23.

CORNER DESIGNATION: A-9, the Northeast Corner of Section 5, Township 3 North, Range 28 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC: Corner was originally established by N.H. Gates under Contract No. 84, dated July 22, 1859. Gates set a post in earth mound. In Survey No. Q-503-B, in 1949, Ofner found a "stake" and remonumented with a 5/8" square bar. Survey No. S-156-C recovered the square bar and remonumented with a 2 1/2" brass cap on pipe monument. Subsequent record surveys have used this monumented position.

MONUMENT AND ACCESSORIES FOUND: Found 2 1/2" brass cap on iron pipe 4" below ground level in unfarmed brush covered area, stamped as shown in Monument Marking Detail.

MONUMENT MARKING DETAIL:

T4N R28E
S32|S33

S5|S4
T3N R28E
1980
PLS 933

MAINTAINED CORNER MONUMENT:

New accessories:

A 5/8"X24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears S 85°44'17" E, 82.66', 6" West of wood post at fence end.

A 5/8"X24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears S 33°15'11" E, 126.80', near guardrail wood post.

A 5/8"X24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 83°27'57" W, 133.36', on East side of railroad tie post.

A 5/8"X24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 71°55'27" W, 12.70', near lone railroad tie post. Attached witness post sign to this railroad tie post.

Attached bearing object signs to wood posts near each rebar accessory.

Courses to corner accessories are State Plane Grid bearings and distances.

LOCATION AND COMMENTS:

OREGON STATE PLANE COORDINATE, North Zone NAD 83(91), International Feet Units:

N: 771680.46
E: 8500117.66

FIRM: Wells Surveying
P.O. Box 1696
Pendleton, OR 97801

Surveyor's Seal

\3N28A-9



RENEWS: 6:30:24

24-004-C