

OREGON CORNER RESTORATION FORM

Section 15 Township 3N Range 28E
 County Umatilla Date: 06-21-02

Corner Designation: 3N28N17

Condition Report Only
 Not Found
 Remonumented
 Unrecorded
 Surveyed In
 Referenced Out


Previous Renewals / Surveys, etc.

Survey H-107-B records setting a brass capped monument here.
 Survey S-119-B records finding a brass capped monument here.


Monument and Accessories Found: (condition and source)

Found the brass capped witness monument described below in good condition.

DIAGRAM



SKETCH



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None.

Made GPS tie to TRI Station
 Stanfield East Base.
 Latitude 45°43'59.39526"N
 Longitude 119°17'24.06298"W
 NAD 83(1991)
 Coordinates are for
 witness corner.

Oregon State Plane Coord. - North Zone
 Northing 755716.81
 Easting 8511056.06
 Ortho Height 630.78
 Ellipsoidal Height 561.15

Location and Comments

Compass Declination
 20 °E

Surveyors Seal

From the junction of Highway 320 and Rosenberg Road, go north for 1.5 mile. Then follow the ditch service road along the south side of Hunt Ditch 0.7 mile to the corner at a pumping station.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

RECEIVED BY:

Firm / Agency

David L. Haddock

Date: 7-02
 Rec'd By: KE
 No. 02-185-g

Haddock Surveying
 P. O. Box 1574
 Pendleton, OR 97801
 (541) 276-2174

OREGON
 JULY 12, 1968
 DAVID L. HADDOCK
 852

RENEWS 6-30-03