

OREGON CORNER RESTORATION FORM

Section 10,15 Township 3N
County Umatilla Date: 05/21/10

Range 29E

Corner Designation: 3N29J15

Corner common to section 10 and 15 T3NR29E.

- Condition Report Only
- Not Found
- Remonumented
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals / Surveys, etc.

Originally Surveyed by Gates in 1859. He set a post in a mound of earth.


Monuments and Accessories Found: (Condition and Source)

None.

Diagram



Sketch



NAD 83/91
OREGON STATE PLANE NORTH
INTERNATIONAL FEET

N761615.69
E8540689.11

LAT - 45° 44' 53.03032" N
LON - 119° 10' 24.96992" W

Monument (s) Set (Procedures and Description)

A 1 1/4" Galvanized Iron pipe w/ 2 1/2" Brass cap stamped as shown above. Set 20" below surface.
Set by single proportionate measure.

References Set: "Deep One" Magnets by Berntsen.

- A Silver magnet, 18" deep lies N 39°40' E, 23.19'.
- A Pink magnet, 18" deep lies S 60° E, 22.17'.
- A Blue magnet, 18" deep lies S 21°50' W, 20.79'.
- An Orange magnet, 15" deep lies N 48°15' W, 27.52'

Location and Comments

The corner is 0.5 miles NE on Hwy 320 out of Echo.

Compass Declination

17° E

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. English
OREGON
JANUARY 11, 2005
ROBERT DOUGLAS ENGLISH
43406LS

RECEIVED BY:

Date: 6-10
Rec'd By: KK
No. 10-96-R

Firm / Agency

Survey One, LLC.
P.O. Box 382
Pendleton, OR 97801
(541) 276-2055

RENEWAL DATE: 12/31/11