## GPS CONTROL STATION

## OREGON STATE PLANE, NORTH ZONE

STATION NAME:

3N29N11

GEODETIC COORDINATE:

NAD 83(91)

SECTION: SW COR \$16

T. 3N., R. 29 E., W. M.

**UMATILLA COUNTY** 

OREGON

REGISTERED PROFESSIONAL AND SURVEYOR

David L. Haddock

HADDOCK

NORTH WITNESS MONUMENT

LAT: LONG: 45°44'1.46284" N 119°11'41.43516" W

STATE PLANE CO-ORDINATES,

NAD 83-91, INT. FT.:

N: E:

756304.478 8535352.422

THETA: SCALE FACTOR: 0°55'32.16" 0.99994321

ELEV:

639

ELEV. DATUM:

NGVD29

FIRM:

HADDOCK SURVEYING

P. O. BOX 1574

PENDLETON, OR 97801

LAT:

45°44'0.45065" N

LONG:

119°11'39.21433" W

STATE PLANE CO-ORDINATES, NAD 83-91, INT. FT.:

N:

756204.516

E:

8535511.581

THETA: SCALE FACTOR: 0°55'33.73" 0.99994316

ELEV:

633

ELEV. DATUM:

NGVD29

**SOUTH WITNESS MONUMENT** 

LAT:

45°43'59.58134" N

LONG:

119°11'41.95634" W

STATE PLANE CO-ORDINATES, NAD 83-91, INT. FT.:

N:

756113.335

E:

8535318.538

THETA: SCALE FACTOR: 0°55'31.79"

0.99994312 640

ELEV:

ELEV. DATUM:

NGVD29

(541) 276-2174

DATE SURVEYED: March, 1998

SURVEYOR: DAVID L. HADDOCK

PLS 852

LOCATION: From main street in the City of Echo go southwest on Oregon Highway 320 to the intersection with Pedro Lane. Go southwest on Pedro Lane to the Westland Main canal and gc west along the main canal approximately 1/2 mile to the entrance road to the feed lot belonging to the Spike Ranches. The corner falls in the river on the east side of the feed lot. The witness caps with the coordinates shown above are approximately 10 feet east of the fence on the east side of the feed lot. There is no monument set at the current corner location.


STATION: Station is in the river and no monument was set. Two witness monuments were set and the coordinates for those points are as shown above. The witness monuments are 2 1/4 inch brass discs on galvanized iron pipes set flush with the surface of the ground.

## **OREGON CORNER RESTORATION FORM**

Section	16	Township	3N	Range	29E	
County	Umatilla	_Date:	<b>April 1, 19</b>			100
Corner Designation: 3N29N11					Condition Report Only Not found	
1/4 corner common to sections 16 and 21,					хх	Remonumented Unrecorded
T3N, R29E, W.M.						Surveyed in
				88	x	Referenced out

Previous Renewals / Surveys, etc.

Corner originally established by Gates in 1859 under contract No. 84 was a post with a 5" balm bearing N25°E, 17 links dist. and a 4" willow bearing S1°W 8 links dist. as a witness corner 137 links north of the true corner point. This point was not set at the mid point of the line east to west Aubrey Perry set a rock with a stake in 1919 in a survey recorded in book 2, page 308 of the record of private surveys. PLS933 found and accepted a wagon axle (not of record) for this corner in Survey S-158-C and set a brass cap for the monument.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)
Set a 2 1/4 inch brass cap on a 1 1/8" x 30" galvanized iron pipe for a witness monument N56°57'00"W, 187.95 feet.

Set a 2 1/4 inch brass cap on a 1 1/8" x 30" galvanized iron pipe for a witness monument S65°38'07"W, 213.49 feet.

The corner position was computed by single proportionate methods using the GLO record of 40.00 chains and 40.60 chains.

## REFERENCES SET:

Location and comments	Compass Declination	Surveyors Seal	
RECEIVED BY: Umatilla County Surveyor Date: 8-98	Firm / Agency Haddock Surveying Address P.O. Box 1574 Pendleton, Or. 97801	REGISTERED PROFESSIONAL LAND SURVEYOR	
Rec'd By: KK No. 98-155- C	Party Chief Stephen K, Haddock	David L. Haddack	
•		OREGON JULY 12, 1968 DAVID L. HADDOCK 852	