| OREGON CORNER RESTORA  | TION FORM                          |  |
|--|------------------------------------|--|
| Section 20,21 Towns County Umatilla Date:                                      | - 15 Maj 1997 - 15                 | Range 29E  |
| County Umatilla Date:  | 03/05/10                           |  |
| Corner Designation: 3N29P9   |                                    |  |
| Corner common to Sections 20,21, T3N   | NR29E.                             | Condition Report Only                                |
|  |                                    | X Not Found X Remonumented                           |
|  |                                    | Unrecorded   |
|  |                                    | X Surveyed InX Referenced Out                        |
| Previous Renewals / Surveys, etc.  |                                    | Neierenced Out                                       |
| Originally Surveyed by Gates. He set a   | post in a mound of earth in 1859.  |  |
|  |                                    |  |
|  |                                    |  |
| Monuments and Accessories Found  | : (Condition and Source)           |  |
| None. This whole area has been regrad  | ded, and smoothed, for center pive | ots.   |
|  | Edge of                            | f Circles  |
| Diagram  |                                    | Sketch   |
| TOW DOOF   | <i>D</i>                           |  |
| T3N R29E   | <b>业</b> /                         |  |
| ( 200   201 )  |                                    |  |
| S20 S21  | \ \                                | Magnets are app.                                     |
| , Di avancia   | •                                  | 1.6' deep.   |
| PLS43406LS<br>2010   |                                    |  |
|  | \                                  | 2 1/2" BC  |
|  |                                    | 0  |
| NAD 83/91  | \                                  |  |
| OREGON STATE PLANE NORTH<br>INTERNATIONAL FEET                                 | \ •                                | <u> </u>   |
|  |                                    | •  |
| N753468.72<br>E8532855.39  |                                    |  |
|  |                                    |  |
| LAT - 45° 43' 33.8609752" N<br>LON - 119° 12' 17.26914421" W                   | 1                                  |  |
|  |                                    |  |
| Monument (s) Set (Procedures and   |                                    |  |
| A 2 ½" Brass cap on a 1" id x 30" galva  | anized Iron pipe, buried 23" below | surface. Cap marked as                               |
| SHOWII above.  |                                    |  |
| References Set: "Deep One" magnets An Orange magnet, 19" deep, lies N 4        | s by Berntsen.                     |  |
| A Silver magnet, 19" deep, lies N 45°2   | 20' E, 14.55'.                     |  |
| A Pink magnet, 19" deep, lies S 28°50<br>A Blue magnet, 18" deep, lies S 47°45 | 'E, 22.35'.                        |  |
| A blue magnet, 10 deep, 1103 0 47 40   | 7 44, 13.30.                       |  |
|  |                                    |  |
| 9 an pan   |                                    |  |
| The corner is 1.2 miles South of the   | Compass Declination<br>17° E       | Surveyors Seal                                       |
| intersection of Hwy 320. and Snow Roa  |                                    |  |
| and .5 miles East .  |                                    | REGISTERED   |
|  |                                    | PROFESSIONAL<br>LAND SURVEYOR                        |
|  |                                    | Ato Do   |
| RECEIVED BY:   | Firm / Agency                      | OREGON ENGLISH                                       |
| RECLIVED BI.   |                                    | OREGON<br>JANUARY II, 2005<br>ROBERT DOUGLAS ENGLISH |
| Date: 3-10   | Survey One, LLC.<br>P.O. Box 382   | 43406LS  |
| Rec'd By:  | Pendleton, OR 97801                | RENEWAL DATE: 12/31/II                               |
| No. 10, 35-A   | (541) 276-2055                     |  |