ERTIFIED RECORD OF LAND CORNER MONUMENTATION

т 3N, R 29E. , W.M.

History of original corner establishment:

This corner was originally established by N. H. Gates, Deputy Surveyor, under Contract No. 84, dated July 22, 1859.

The original notes state:

"Set post for 1/4 Sec. corner in mound of Earth & @ as per instructions."

Corner Code No. T-21 Note: Monument marked as shown below

DIAGRAM

T3N R29E 1/4 S261S25

> 1992 PLS 1106

Corner No. Compass Declination: 18.0°

Description of corner evidence found:

Long standing fence with fences extending South and West. After confirming corner location by survey, I accept the fence corner as the best remaining evidence of the original corner location and remonument the corner point as indicated below.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2 1/2" Brass cap on a 1 1/4" by 30" G.I.P. 24" in ground and surrounded with a mound of earth, from which:

A 5/8" by 30" rebar bears S 89 1/4°W - 15.71 feet, with a Bearing Object sign nailed to nearby railroad tie. A 5/8" by 30" rebar bears S 89 1/4°W - 69.72 feet. A 5/8" by 30" rebar bears S 0 1/4°E - 26.92 feet. A 5/8" by 30" rebar bears S 0 1/4°E - 57.69 feet.

Each rebar is capped with a yellow plastic cap marked "W.R. Wells, PLS 1106". A steel fence post was set by the last 3 rebar cited above, with a Bearing Object sign attached.

Nailed a Witness Corner sign to railroad tie fence post near monument.

Fences go South and West.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

R. Wells

State of......, I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... (COUNTY OFFICIAL) (DEPUTY)

RECEIVED BY

Form R6-7100-57 (9/71)

Umatilla County Surveyor

Rec'd By

☆ GPO-798-276