## CORNER RESTORATION FORM

Township 3N Range 30E Section 1,2,11&12 County UMATILLA State OREGON Date 4-7-2015 Number E-21 \_ Condition Report Only Not Found Corner Designation: SECTION 1, 2, 11 & 12 \_ Renewed \_ Surveyed In Previous Renewals ORIGINAL SOURCE OF CORNER X Referenced UNDER GLO CONTRACT #95 BY W. CAMPBELL DATED SEPTEMBER 19, 1860 SET POST MONUMENT DETAIL X Set Found Accessories Found: T3N R30E NONE BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE: S2 SI S11 | S12 NORTHING: 767560.885 2015 PLS 61420 EASTING: 8580761.101

Monument & Accessories Set (Procedure and Description)

SET 2 1/2" BRASS CAP ON 1 1/4"x30" PIPE 0.2' ABOVE GRADE SOUTH SIDE OF RAILROAD TIE POST SURVEY

MARKER SIGN ON THE RAILROAD TIE POST.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, BEARING OBJECT SIGN ON T-POST, N84°38'E 20.27'.

SET 5/8" REBAR & CAP PLS 61420 1' BELOW GRADE, S20°34'W 15.15'.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE IN FENCE LINE, N88°03'W 112.45'.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, BEARING OBJECT SIGN ON T-POST, N3°32'W 36.27'.

