OREGON CORNER RESTORATION		
OREGON CORNER RESTORATION Section 12 Township		
Section 12 Township County Umatilla Date:	3N	Range 29E
Date.	08/20/10	
Corner Designation: 3N29G25		
1/4 Corner common to section 12, T3NR29E	and section 7. T3NR30F	
	, and a second of the second	X Not Found
		X Remonumented
		Unrecorded
		X Surveyed In
		X Referenced Out
Previous Renewals / Surveys, etc.		
Originally Surveyed by David P. Thompson	n 1859. He set a post in a	mound of earth.
Monuments and Accessories Found: (Co	ndition and Course	
None	nullion and Source)	
Diamon		
Diagram		Sketch
T3N TIND	Orange Magnet .	Silver Magnet
R29E R30E	Orange Magnet •	→ 38
(S12 ∮ S7)		
(312 7 37		
ORPLS 43406LS		
2010		O 19" Deep
		BC
NAD 83/91		
OREGON STATE PLANE NORTH		
INTERNATIONAL FEET	Blue Magnet •	 Pink Magnet
N764541.21		· ····· ······························
E8553804.62		
2000004.02		
LAT - 45° 45' 19.74253" N		
LON - 119° 07' 19.33746" W		
Monument (s) Set (Procedures and Descr	iption)	
Set A 1"x30" flared galvanized iron pipe with	a 2 1/2" B.C. by single pro	portionate method.
	2	
References Set: "Deep One" magnets by Be		
An Orange magnet 18" deep, lies N 12°20' E A Silver magnet 18" deep, lies N 46°20' E, 18		
A Pink magnet 18" deep, lies S 4°00' E, 18.3		
A Blue magnet 17" deep, lies S 69°00' W, 18		
The state of the s	.20.	
Location and Comments	Compass Declination	Surveyors Seal
Corner is in an active wheat field	17° E	encomon ನಿನ್≇ ನಾಡುವಾಡದ್*)
approx $\frac{1}{8}$ mi. S of farm road, and approx		
¹ / ₄ mi W of existing farm house. N of I-84.		REGISTERED
11 VIII VIII VIII VIII VIII VIII VIII V		PROFESSIONAL
		LAND SURVEYOR
		1.10.00
		Foot - English
RECEIVED BY:	Firm / Agency	OREGON JANUARY II, 2005
	Survey One, LLC.	ROBERT DOUGLAS ENGLISH
Date: 8-10	P.O. Box 382	43406LS
Rec'd By: *	Pendleton, OR 9780	1 RENEWAL DATE: 12/31/09
No. 10-140-R	(541) 276-2055	
70 110	7	