CORNER RESTORATION FORM

Township 3N Range	Sec	tion 13 & 14 (County <u>UMATILIA</u>
State_OREGONDate_	9-29-2014 Nur	nber <u>L-21</u>	
Corner Designation : 1	/4 SECTION 13 &	14	Not Found Renewed
Previous Renewals OR	IGINAL SOURCE OF	CORNER	Surveyed In
			Referenced
UNDER GLO CONTRACT #84 BY JULY 22, 1859 SET POST	I N. GATES DATED		MONUMENT DETAIL
3011 20, 1000 021 1001			X Found Set
Accessories Found:			set
NONE			T3N R30E
			1/4
BASIS OF BEARINGS, NAD 83 COORDINATES NORTH ZONE:	3/91 OREGON STA	ATE PLANE	S14 @ S13
	NORTHING: 7		2007
	EASTING: <u>85</u>	<u> </u>	56295LS
Monument & Accessories Set (Procedure and De	scription)	
FOUND 2 1/4" BRASS CAP 6" E	BELOW ROAD GRADE	. PER SURVEY No.	07-245-R.
Sketch of Monument,			
	GOAD	ASS'RE	PROFESSIONAL LAND SURVEYOR
4	LORENZEN ROAD (GRAVEL)	GRASSY PASTURE	
GRASEY PASTURE	RENZ (GRA		Jane Pliny
PAU	LOF		ORESON MAY 10, 2941
)		LANCE CLARK KING 61420
	'		
			RENEWS: 6/30/2017 Agency:
			CK3, LLC
FOUND 2 1/4" BRASS CAP			945 W. ORCHARD HERMISTON OREGON 97838 OFFICE: 541-567-2345
6" BELOW ROAD GRADE.			FAX: 541-567-2305 WEB: CK3LLC.NET
		PEEBLER ROA (GRAVEL)	D Field Book # 0-298
		(GIAVILI)	COUNTY SURVEYOR RECORDING INFO
OHP	— — OHP — —	OHP -	- Received Lay Wat
OH — —	— — OHF — —	- T — OHF —	· / / ·
, and a			
GRACURE	l .		10 N 16-050-C
PASI		GRA	Survey No. <u>15-050-C</u>
GRASSY PASTURE		GRA PA	Survey No. <u>15-050-C</u> Drawing No. <u>L-21</u> Index No. <u>L-21</u>