## CORNER RESTORATION FORM

Township 3N Range 30E Section 16,15,21&22 (	County <u>UMATILLA</u>
State OREGON Date 3-12-2015 Number N-13	Condition Report Only
Corner Designation : SECTION 16, 15, 21 & 22	Not Found Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER	X Surveyed In X Referenced
UNDER GLO CONTRACT #95 BY W. CAMPBELL DATED	
SEPTEMBER 19, 1860 SET POST	MONUMENT DETAIL
	FoundX Set
Accessories Found:	
NONE	T3N R30E
	S16   S15
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE:	S16   S15 S21   S22
NORTHING: 756845.738	2015
EASTING: <u>8570373.383</u>	PLS 61420

## Monument & Accessories Set (Procedure and Description)

SET 2 1/2" BRASS CAP ON 1 1/4"x30" PIPE 2' BELOW FIELD GRADE.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, N1°50'E 249.07', NEAR POWER POLE TO SOUTH.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S7º16'E 114.26', BEARING OBJECT SIGN ON POWER POLE.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S30°12'W 100.18', BEARING OBJECT SIGN ON FENCE POST IN FENCE LINE.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S85°00'W 206.43', IN FENCE LINE.

