

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla    DATE: 2/25/16

CORNER DESIGNATION: R-23, The South Quarter Corner of Section 24, Township 3 North, Range 30 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally set by Wm. Campbell under Contract No. 95, dated September 19, 1860. Notes state; set a post for ¼ sec. corner, drove a charred stake, raised mound of earth per instructions.

MONUMENT AND ACCESSORIES FOUND: None. There are no features at corner location. Held a calculated position on parallel of latitude, midway between Section corners on each side. See survey filed concurrently with this certificate for further information.

**MONUMENT MARKING DETAIL:**

T3N R30E  
1 S24  
4 S25  
2016  
PLS 54657

MONUMENT SET: At the calculated corner point set a 2 3/8" brass cap on 1 ¼"x30" galvanized iron pipe with top 22" below ground level in farmed field. Monument marked as shown in "Monument Marking Detail".

**From which:**


A pink Deep-1 magnet buried 22" below ground bears 42°44'27" (grid azimuth), 27.4 feet.  
A silver Deep-1 magnet buried 22" below ground bears 138°28'55" (grid azimuth), 30.9 feet.  
A blue Deep-1 magnet buried 22" below ground bears 205°56'43" (grid azimuth), 32.4 feet.  
A orange Deep-1 magnet buried 22" below ground bears 321°21'25" (grid azimuth), 30.6 feet.  
Buried bearing object signs with magnets.

LOCATION AND COMMENTS: Corner is located in a farmed field. No visible features. See map filed concurrently with this certificate for further information.

FIRM: Wells Surveying  
P.O. Box 1696  
Pendleton, OR 97801

COMPASS DECLINATION: 18° East                      Surveyor's Seal

/3N30R23



RENEWS: 6:30:16

16-029-B