CORNER RESTORATION FORM

Township 3N Range 30E & 31E Section 1 & 6	County_UMATILLA
State OREGON Date 3-11-2015 Number C-25	Condition Report Only
Corner Designation: 1/4 SECTION 1 & 6	Not Found Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER	X Surveyed In X Referenced
UNDER GLO CONTRACT #81 BY D. THOMPSON DATED	
JULY 8, 1859 SET POST	MONUMENT DETAIL
	FoundX Set
Accessories Found:	
NONE	T3N R30E R31E
	1001/4
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE:	S1 S6
NORTHING: 770510.607	2015
EASTING: 8585977.192	PLS 61420
Monument & Accessories Set (Procedure and Description)	

SET 2 1/2" BRASS CAP ON 1 1/4"x30" PIPE 0.5' ABOVE GRADE IN FENCE LINE, MARKER SIGN.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, N1°09'W 20.91', IN FENCE LINE, BEARING OBJECT SIGN.

SET 5/8" REBAR & CAP PLS 61420 1.5' BELOW GRADE, S75°40'E 6.76'.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S1°48'E 29.50' IN FENCE LINE, BEARING OBJECT SIGN.

SET 5/8" REBAR & CAP PLS 61420 1.5' BELOW GRADE, N81°08'W 19.27'.

