CORNER RESTORATION FORM

Township 3N Range 30E & 31E Section 12 & 7 County U	JMATILLA
State OREGON Date 3-10-2015 Number G-25	_ Condition Report Only
Corner Designation: 1/4 CORNER SECTION 12 & 7	_ Not Found
\mathbf{x}	_ Renewed _ Surveyed In
Previous Renewals Unidinal Source of Corner	_ Surveyed in _ Referenced
UNDER GLO CONTRACT #81 BY D. THOMPSON DATED	
JULY 8, 1859 SET POST MONU	JMENT DETAIL
Found	_X Set
Accessories Found:	T3N
NONE	R30E R31E
	4
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE:	S12 S7
NORTHING: <u>765202.721</u>	2015
EASTING: <u>8586061.378</u>	PLS 61420
Monument & Accessories Set (Procedure and Description)	
SET 2 1/2" BRASS CAP ON 1 1/2" PIPE 0.5' ABOVE GRADE IN FENCE LINE WITH MARKER SIGN.	
SET 5/8" REBAR & CAP PLS 61420 AT GRADE, N1°20'W 22.95', IN FENCE LINE.	
SET 5/8" REBAR & CAP PLS 61420 1' BELOW GRADE, N45*11'E 11.06'.	
SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S0°41'E 107.19', BEARING OBJECT	T SIGN ON RAILROAD TIE.
SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S42°39'W 37.34', AT THE NE COR	NER OF TIN ROOF, BEARING
OBJECT ON GREEN STEEL POST.	
Sketch of Monument, Accessories and General Area	REGISTERED
	PROFESSIONAL LAND SURVEYOR
EX. WIRE FENCE SET 5/8" REBAR & CAP PLS 61420 AT GRADE IN	
FENCE LINE	Samefling
GRASSY E E	OREGON
N Ab	MAY 10, 2011 LANCE CLARK KING
SET 5/8" REBAR & CAP PLS 61420 1'	61420
SET 5/8" REBAR & CAP × .c.	RENEWS: 6/30/2015
PLS 61420 AT GRADE AT THE NE CORNER OF TIN	Agency:
ROOF, BEARING OBJECT ON GREEN STEEL POST	CK3, LLC 945 W. ORCHARD
200'W	HERMISTON OREGON 97838 OFFICE: 541-567-2345
S422334 ×	FAX: 541-567-2305 WEB: CK3LLC.NET Field Book# 0-289
SET 2 1/2" BRASS CAP ON	
1 1/4"x30" PIPE AT GRADE IN FENCE LINE, MARKER	COUNTY SURVEYOR RECORDING INFO
TIN ROOF WILDLIFE WATERER TIN ROOF WATERER	Received Day Topet
WAIERER X	heceived 5/12/2015

EX. RAILROAD TIE

Survey No. 15-050-C

G-25

Drawing No.<u>C-853</u>

Index No.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE & BEARING OBJECT SIGN ON RAILROAD TIE