

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 4/13/15

CORNER DESIGNATION: The North One-Quarter Corner of Section 16, Township 3 North, Range 31 East, J-11.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by D.S. Payne, under Contract No. 100, dated 8/1/1861, notes state: Set charred stake with mound trench and pits as per instrs. for 1/4 sec corner.

MONUMENT AND ACCESSORIES FOUND: None.

MONUMENT MARKING DETAIL:

T3N R31E
1 S9
4 S16
2015
PLS 54657

MONUMENT SET:

Re-established corner on parallel of latitude between the Southwest and Southeast corners of Section 9, holding North-South field berm for departure and set a 2 3/8" brass cap on a 1 1/4" x 30" galvanized iron pipe, 2" below ground level, stamped as shown in "Monument Marking Detail".

From which:

- A 5/8" x 24" rebar with a 1 1/4" blue plastic cap stamped "Wells Surveying, PLS 54657", 2" above ground level, in ditch bank, bears South 09° East, 47.3 feet.
- A 5/8" x 24" rebar with a 1 1/4" blue plastic cap stamped "Wells Surveying, PLS 54657", 2" above ground level, in ditch bank, bears South 06° East, 24.2 feet.
- A 5/8" x 24" rebar with a 1 1/4" blue plastic cap stamped "Wells Surveying, PLS 54657", 2" above ground level, in ditch bank, bears North 63° West, 34.7 feet.
- A 5/8" x 24" rebar with a 1 1/4" blue plastic cap stamped "Wells Surveying, PLS 54657", 2" above ground level, in ditch bank, bears North 64° West, 59.1 feet.

Wired bearing object tags to rebars. Set steel fence post with witness sign attached 1 foot North of monument.

LOCATION AND COMMENTS: Corner falls in a North-South field berm projection, in scab area.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 762640.68
E = 8599452.76

FIRM: Wells Surveying
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East Surveyor's Seal

Witnesses: Jason Wells, PLS
Dean Roy

/3N31J11

15-052-c



RENEWS: 6-30-16