

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla DATE: 03/8/06

CORNER DESIGNATION: 3N31, N-3, The South One-Quarter Corner of Section 18.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner established by D. S. Payne, under Contract No. 100, dated August 1, 1861. Record states: Set charred stake with mound, trench and pits as per insts. for 1/4 sec. corner.

**MONUMENT AND ACCESSORIES FOUND:**

Accepted the intersection of Yoakum Road, running North-South running road, and field lines running East and West, as best remaining evidence of the original corner position.

**MONUMENT MARKING DETAIL:**

T3N R31E  
1 S18  
4 S19  
2006  
PLS 1106

**MONUMENT SET:**

At reestablished corner position, set a 2 3/8 " brass cap on 1 1/4" x 30" galvanized iron pipe with cap buried 12" below road surface. Monument marked as shown in monument marking detail.

From which:

A silver Deep-1 magnet buried 24" in the ground bears North 38 1/2° East, 37.3 feet.

A 3/4" brass washer stamped "PLS 1106" 1 foot above ground in a railroad tie fence post bears South 87° East, 19.5 feet.

A purple Deep-1 magnet buried 24" in the ground bears South 37° West, 46.5 feet.

A 5/8" x 24" iron rebar with 1 1/4" yellow plastic cap marked "OR PLS 1106 WA PLS 17372" bears South 82 1/2° West, 21.7 feet.

Attached bearing object signs to rebar accessory and railroad tie fence post with brass washer.

Buried bearing object signs with magnets. Nailed witness sign to railroad tie fence post South 87° East, from monument.

LOCATION AND COMMENTS: Corner is located at the intersection of Yoakum Road running North-South, and field berms East and West.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 757258.92

E = 8589026.02

FIRM: William R. Wells, PLS

P.O. Box 1696

Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

/3N31N3

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Will. R. Wells*  
OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-08*