OREGON CORNER RESTORATION FORM						
Section: County:	23, 24, 25, 26 Umatilla	Township: 3N Date: 1/18/2012	Range:	33E		
Corner Designation: 3N33R21						
Section corner common to Sections 23, 24, 25, 26, T3NR33E. Condition Report Only						
				X	Not Found Remonumented	
					Unrecorded	
				X	Surveyed In Referenced Out	
Previous Renewals / Surveys, etc. Originally surveyed by Chaplin in 1864. He set a post in a mound of earth, with charred stake and pits. In 1871 Moody set a post in a mound of earth. In 1887 Currin and Noland set a post in a mound of earth and dug pits in each section.						
Monuments and Accessories Found: (Condition and Source): None.						
Diagram Sketch					1	
	NR33E		ORANG MAGNE		SILVER MAGNET	
S26 S25 PLS43406LS						
OBC						
NAD 83/91 OREGON STATE PLANE NORTH INTERNATIONAL FEET TUBBS RANCH RD.						
N753225					•IR	
E8676603	.75			SFP	PINK MAGNET	
Monument(s) Set (Procedures and Description): A 1 1/8" x 30" galvanized iron pipe with 2 1/2" brass cap, stamped as shown above, 1.1' below the surface of Tubbs Ranch Rd. The corner location was reestablished at the intersection of the road centerline and the field line to the South. This provides a good fit to the GLO distance from the East.						
An orange A silver m A pink ma	e" magnets by Bern e magnet lies N 32° agnet lies N 45° 50' gnet lies S 44° 30' I	20' W, 20.92', 1.5' (E, 26.53', 1.5' deep E, 30.49', 1.5' deep.	o	North side of a ste	el fence post.	
The come	and Comments: or is located 0.4 mile on of Hwy. 11 and Ti	s East of the	npass Declination 17° E	Surv	reyors Seal	
Rd.	VED BY:	INITIALITY	Firm / Agency Survey One, LLC.	PRO LAND Robert D	GISTERED FESSIONAL D SURVEYOR OREGON JARY II, 2005 BOUGLAS ENGLISH 43406LS	
Date: _ Rec'd E	7/10/2012		P.O. Box 382 Pendleton, OR 9780			
No	12-094-6	<u></u>	(541) 276-2055	RENEWA	L DATE: 12/31/13	