OREGON	CORNER R	RESTORATION	FORM						
Section: County:	36, 31 Umatilla	Township: Date: 10/31/	3N	Range:	33E,	34E			
Corner Des	ignation:	3N33X25							
Quarter corner common to Sections 36, T3NR33E; 31				NR34E.	X Condition Report Or Not Found Remonumented Unrecorded Surveyed In X Referenced Out		ed		
Originally so In 1871 Mod	ody set a post i	veys, etc. ompson in 1864. He in a mound of earth ass cap in Survey ().	n a mound of	earth	with charred s	itake, pits, and	trench.	
		ories Found: (Con ed as shown below							
Dia	gram					Sketch			
NAD 83/91 OREGON	1/4 5 S31 5 R34E 73N 5 933 971	ENORTH		ORANGI MAGNE		BC O← 15'	SFP IR		
N745407 E8682018				BLUE		PII	FIELD LINE NK !	•	
Monumen None.	t(s) Set (Proce	edures and Descr	iption):	MAGNET			AGNET		
An orange A 5/8" x 30 A pink ma	e" magnets by to magnet lies N O" iron rebar lie gnet lies S 38°	Berntsen. 38° 50' W, 17.78', s N 31° 10' E, 36.1 50' E, 29.93', 1.4' o 50' W, 26.89', 1.5'	3' <u>.</u> leep.						
The come	st of the interse	<u>s:</u> mile South and ection of Duff Rd.	Compass D 17° E			REG PROF	SISTERED ESSIONAL SURVEYOR		
	VED BY:	 	Survey	Agency One, LLC.		JANU ROBERT DO	DREGON ARY II, 2005 OUGLAS ENGLIS	SH	
Date:			Pendle	P.O. Box 382 Pendleton, OR 97801 (541) 276-2055			RENEWAL DATE: 12/31/13		