Photo No. Roll 29# 29-26 Ident, By: J. Berlin,

7. Photo Identification 7-17-61

8. Plane Coordinate Position Data State____Zone_ Estab. By____

Field Book No._ Where Filed

No

- 9. Evaluation
- Authentic_

- Needs Verif._X_Monument
- Re-estab.___Survey_ Land Status_

- Umatilla Dist Pendleton// 3. Original Description_ Page__32 ___ Vol.___ Where Recorded GLO year 1878
 - 4. Description of Corners: Set stone 18x10x8 on Recky point facing S.E. for corners to section 27,28,33, & 34, from which: Fir 20 inches diameter bears S 120 E 107 links distant. Fir 12 inches diameter bears S 48° W 96 links distant. No trees on North side.
- Investigation Notes: Using USGS notes and aerial photos as guide, we traveled south up Ryan Creek to search area indicated by photo. Found dead 6" cottonwood with K. tag stating the sec. corner was west approx. 42 chains. Found 22" fir B.T. markings were T.3.N. R. 36 E Sec. 33 at botton the scribbing looked like: S 48° W. The S, 4, & W was destroyed or not cut out. Other B.T. missing, but there is an old stump believed to be the B.T. We went N 48° E 96links from 22" fir B.T. We found a rock that may be the sec. corner. We sprayed silver paint on rock, placed B.T. sign on 22" fir. Sub. pt. 12" P.P. on S.E. exposure in opening with erange ribbon and silver paint on bears S 180 W 110 links dist. to stone from 16" P.P. known B.T. Fir at this point is a dead Fir snag, with good blaze. Best way in is up Ryan Creek just before making one of the creek crossing, there is a 16" Fir on right side of trail with

silver paint and orange ribbon, then go west approximately 4 1/2 chains.

Signed A.L. Salbrath Title Range Technician 5-19-64

P	ER	P	E.	Τι	J/	۱Т	ΊC	/(1	R	Έ	С	O	F	ł	
---	----	---	----	----	----	----	----	----	---	---	---	---	---	---	---	--

11. Accessories

10. Monument:

			,	Field Book	Page
12. Set By	Title		13. Recorded By(Agen	volume	Page
License	Agency	Date	(Date) (City)	(Ceunty)	(State) · · ·

14. Remarks:

/-/3